



Transportation  
Safety Board  
of Canada

Bureau de la sécurité  
des transports  
du Canada



# AIR TRANSPORTATION SAFETY INVESTIGATION REPORT A22Q0126

## COLLISION WITH TERRAIN

Collège d'enseignement général et professionnel de Chicoutimi  
Beech Aircraft Corporation C23 Sundowner, C-GBQI  
Chicoutimi/St-Honoré Airport, Quebec  
21 October 2022

The Transportation Safety Board of Canada (TSB) investigated this occurrence for the purpose of advancing transportation safety. It is not the function of the Board to assign fault or determine civil or criminal liability. **This report is not created for use in the context of legal, disciplinary or other proceedings.** See the Terms of use at the end of the report.

### History of the flight

At 0840<sup>1</sup> on 21 October 2022, the chief flight instructor (CFI) for the Collège d'enseignement général et professionnel (CEGEP) de Chicoutimi<sup>2</sup> at the Chicoutimi/St-Honoré Airport (CYRC), Quebec, was tasked with conducting an evaluation flight following a student pilot's first solo flight. The goal of the flight was to evaluate the student pilot's progress and ability to conduct takeoffs, initial climbs, circuits, approaches, landings, go-arounds, and emergency procedures.

The student pilot conducted a pre-flight inspection of the Beech Aircraft Corporation C23 Sundowner aircraft (registration C-GBQI, serial number M-2264) and noted that the aircraft had 15 U.S. gallons of fuel in each tank (30 U.S. gallons total). Following the pre-flight inspection,

<sup>1</sup> All times are Eastern Daylight Time (Coordinated Universal Time minus 4 hours).

<sup>2</sup> The Collège d'enseignement général et professionnel de Chicoutimi's flight training unit does business as the Centre québécois de formation aéronautique.




At 1019, the CFI called the tower controller to request a right-hand circuit at 500 feet AGL, which was approved. The student pilot had no previous experience conducting right-hand circuits from Runway 30, or circuits at 500 feet AGL. The goal of the right-hand circuit was to demonstrate the difference between a tailwind and a headwind on a simulated engine failure while on the base turn.

While the aircraft was on the right downwind leg for Runway 30 at approximately 500 feet AGL, the CFI initiated a simulated engine failure and informed the tower controller of the exercise. The student pilot turned the aircraft toward the Runway 30 threshold but determined that they would not be able to reach the runway. The student pilot suggested aiming for a nearby field. After a quick discussion between the CFI and the student pilot, it was decided to aim for Taxiway B.

As the aircraft was heading towards Taxiway B, it became evident to the student pilot and the instructor that they were not going to reach the intended landing point. The aiming point was then altered to a cleared gravel area short of Taxiway B. At approximately 1022, the aircraft's right wing contacted small trees and the aircraft collided with terrain in the cleared gravel area (Figure 2). At no point during this simulated-engine-failure exercise was an overshoot initiated by either the student pilot or the CFI.

**Figure 2. Flight track from the start of the simulated engine failure to the point of impact**  
(Source: Google Earth, with TSB annotations)



The CFI and student pilot were both wearing the available 3-point safety harnesses. Once the aircraft came to a stop, they were able to egress through the aircraft doors. Both received minor injuries.

The aircraft was destroyed. The emergency locator transmitter activated. There was no fire.

## Pilot information

### Chief flight instructor

The CFI was hired by CEGEP de Chicoutimi in 2009 and became the flight training unit's CFI in 2015. At the time of the occurrence, he had accumulated approximately 7000 hours total flight time, of which approximately 2500 hours were instructional hours. He held an airline transport pilot licence – aeroplane and a Class 2 flight instructor rating. The CFI was the pilot-in-command<sup>3</sup> of the flight.

### Student pilot

The student pilot held a student pilot permit and had begun flight training in August 2022. At the time of the occurrence, the student pilot had accumulated approximately 15 hours total flight time.

## Weather information

The nearest weather reporting station to CYRC is Bagotville Airport (CYBG), Quebec, located 11 nautical miles to the south-southeast. At 1000, the weather was reported to be:

- Winds from 230° true at 7 knots
- Visibility of 25 statute miles
- Few clouds at 4000 feet AGL
- Temperature 8 °C and dewpoint 0 °C

## Aircraft information

The Beech Aircraft Corporation<sup>4</sup> C23 Sundowner is a 4-seat, low-wing, tricycle-gear aircraft equipped with a single 4-cylinder piston engine. The occurrence aircraft was built in 1980 and had accumulated 8279.6 hours since new. The aircraft has a fuel capacity of 59.8 U.S. gallons (29.9 U.S. gallons in each wing fuel tank).<sup>5</sup> The aircraft's pilot operating handbook prohibits a takeoff "when Fuel Quantity Gages [*sic*] indicate in Yellow Band on either gage [*sic*]."<sup>6</sup> The yellow band of the fuel gauges corresponds to a tank fuel level between empty to 1/3 full,<sup>7</sup> which is approximately 10 U.S. gallons per tank. Therefore, taking into consideration the planned flight time of the evaluation flight, the fuel on board the aircraft (30 U.S. gallons) was sufficient for the intended flight.

The investigation did not uncover any defects with the aircraft before the collision with the terrain.

<sup>3</sup> Pilot-in-command "means, in relation to an aircraft, the pilot having responsibility and authority for the operation and safety of the aircraft during flight time" (Source: Government of Canada, *Aeronautics Act* [R.S.C., 1985, c. A-2], subsection 3[1].)

<sup>4</sup> The current type certificate holder is Textron Aviation Inc.

<sup>5</sup> Beech Aircraft Corporation, *Beechcraft Sundowner 180 C23 Pilot's Operating Handbook and FAA Approved Airplane Flight Manual*, Revision A7 (July 1994), Section I: General, Descriptive Data – Fuel, p. 1-10.

<sup>6</sup> *Ibid.*, Section II: Limitations, Fuel Management, p. 2-19.

<sup>7</sup> *Ibid.*, Miscellaneous Instrument Markings – Fuel Quantity, p. 2-7.



## Wreckage examination

The aircraft came to a rest in a gravel area to the east of Taxiway B. It sustained substantial damage to its nose, wings, and gear (Figure 3). The cockpit survivable space remained intact, and the cockpit doors were useable.

Figure 3. Aircraft wreckage (Source: Third party, with permission)



The trees that the aircraft contacted were approximately 20 feet tall and had previously lost their leaves, which made them difficult to see because there was little contrast with the surrounding gravel area (Figure 4).

Figure 4. Area of collision with trees, with a close-up view in inset, showing the lack of contrast between the trees and the background (Source: TSB)



## Flight training unit

The CEGEP de Chicoutimi is a Transport Canada approved flight training unit. It is authorized to conduct training for private and commercial pilot licences, as well as for numerous pilot ratings.

The flight training unit normally assigns 1 instructor to each student for private pilot licence training. Then, as part of the structured flight training syllabus, a different instructor will conduct certain evaluation flights, such as the evaluation after the student pilot's first solo flight. The objective of this evaluation flight is to determine if the pilot is capable of further solo flights. The student pilot is graded on the flight.

### **Minimum altitude guidance**

Transport Canada's *Flight Training Manual – Aeroplane* provides "basic, progressive study material for student pilots preparing for licensing, pilots improving their qualifications, and for the guidance of flight instructors."<sup>8</sup>

The *Flight Training Manual – Aeroplane* states that for simulated engine failure exercises,

[w]ith the exception of those approaches made to an aerodrome, all simulated forced landings should be practised in the local practice area, and only to the minimum altitude specified by the *Canadian Aviation Regulations* or the training unit when they are more restrictive.<sup>9</sup>

The *Canadian Aviation Regulations* require aircraft to remain at least "500 feet from any person, vessel, vehicle or structure"<sup>10</sup> except when taking off and landing, or "where the aircraft is operated without creating a hazard to persons or property on the surface and the aircraft is operated for the purpose of [...] flight training conducted by or under the supervision of a qualified flight instructor."<sup>11</sup>

At the time of the occurrence, the flight training unit did not have a policy that established a minimum overshoot altitude for simulated engine failures leading to an off-runway landing, and did not have standard phraseology for an overshoot call.

### **TSB laboratory reports**

The TSB completed the following laboratory report in support of this investigation:

- LP103/2022 – NVM Recovery – MFD

### **Safety action taken**

After this occurrence, the CEGEP de Chicoutimi introduced the following:

- a policy that sets a minimum altitude of 200 feet AGL for simulated engine failure exercises, unless the approach and landing is to a runway;
- a standard overshoot call; and
- a ban on conducting circuits at 500 feet AGL.

<sup>8</sup> Transport Canada, TP 1102, *Flight Training Manual – Aeroplane*, 4<sup>th</sup> edition (revised 2004), Preface, p. v.

<sup>9</sup> Ibid., Exercise Twenty-Two: Forced landing, Simulated engine failure, p. 131.

<sup>10</sup> Transport Canada, SOR/96-433, *Canadian Aviation Regulations*, paragraph 602.14(2)(b).

<sup>11</sup> Ibid., subparagraph 602.15(2)(b)(iv).

## Safety messages

Operating aircraft at low altitudes, as is done during a simulated engine failure to a landing exercise, increases the risk of collision with obstacles and/or terrain. The pilot-in-command must consider the operating environment and ensure that adequate safety margins are maintained to allow sufficient reaction time to avoid obstacles or to respond to an aircraft malfunction.

This report concludes the Transportation Safety Board of Canada's investigation into this occurrence. The Board authorized the release of this report on 03 January 2024. It was officially released on 19 janvier 2024.

Visit the Transportation Safety Board of Canada's website ([www.tsb.gc.ca](http://www.tsb.gc.ca)) for information about the TSB and its products and services. You will also find the Watchlist, which identifies the key safety issues that need to be addressed to make Canada's transportation system even safer. In each case, the TSB has found that actions taken to date are inadequate, and that industry and regulators need to take additional concrete measures to eliminate the risks.

## ABOUT THIS INVESTIGATION REPORT

This report is the result of an investigation into a class 4 occurrence. For more information, see the Policy on Occurrence Classification at [www.tsb.gc.ca](http://www.tsb.gc.ca)

The Transportation Safety Board of Canada (TSB) investigated this occurrence for the purpose of advancing transportation safety. It is not the function of the Board to assign fault or determine civil or criminal liability.

## TERMS OF USE

### Use in legal, disciplinary or other proceedings

The Canadian Transportation Accident Investigation and Safety Board Act states the following:

- 7(3) No finding of the Board shall be construed as assigning fault or determining civil or criminal liability.
- 7(4) The findings of the Board are not binding on the parties to any legal, disciplinary or other proceedings.

Therefore, the TSB's investigations and the resulting reports are not created for use in the context of legal, disciplinary or other proceedings.

Notify the TSB in writing if this investigation report is being used or might be used in such proceedings.

### Non-commercial reproduction

Unless otherwise specified, you may reproduce this investigation report in whole or in part for non-commercial purposes, and in any format, without charge or further permission, provided you do the following:

- Exercise due diligence in ensuring the accuracy of the materials reproduced.
- Indicate the complete title of the materials reproduced and name the Transportation Safety Board of Canada as the author.
- Indicate that the reproduction is a copy of the version available at [URL where original document is available].

### Commercial reproduction

Unless otherwise specified, you may not reproduce this investigation report, in whole or in part, for the purposes of commercial redistribution without prior written permission from the TSB.

### Materials under the copyright of another party

Some of the content in this investigation report (notably images on which a source other than the TSB is named) is subject to the copyright of another party and is protected under the *Copyright Act* and international agreements. For information concerning copyright ownership and restrictions, please contact the TSB.

### Citation

Transportation Safety Board of Canada, *Air Transportation Safety Investigation Report A22Q0126* (released 19 January 2024).

Transportation Safety Board of Canada  
200 Promenade du Portage, 4th floor  
Gatineau QC K1A 1K8  
819-994-3741; 1-800-387-3557  
[www.tsb.gc.ca](http://www.tsb.gc.ca)  
[communications@tsb.gc.ca](mailto:communications@tsb.gc.ca)

© His Majesty the King in Right of Canada, as represented by the Transportation Safety Board of Canada, 2024

Air transportation safety investigation report A22Q0126

Cat. No. TU3-10/22-0126E-PDF

ISBN: 978-0-660-69533-4

This report is available on the website of the Transportation Safety Board of Canada at [www.tsb.gc.ca](http://www.tsb.gc.ca)

*Le présent rapport est également disponible en français.*