



Transportation
Safety Board
of Canada

Bureau de la sécurité
des transports
du Canada



AIR TRANSPORTATION SAFETY INVESTIGATION REPORT A21W0071

COLLISION WITH TERRAIN

Privately registered
Mooney M20C, C-GTIJ
Slave Lake Airport, Alberta, 12 NM NE
31 August 2021

The Transportation Safety Board of Canada (TSB) investigated this occurrence for the purpose of advancing transportation safety. It is not the function of the Board to assign fault or determine civil or criminal liability. **This report is not created for use in the context of legal, disciplinary or other proceedings.** See the Terms of use at the end of the report.

History of the flight

On 31 August 2021, the privately registered Mooney M20C aircraft (registration C-GTIJ, serial number 2901) was conducting a visual flight rules (VFR) flight from La Crête Aerodrome (CFN5), Alberta, to Saskatoon/John G. Diefenbaker International Airport (CYXE), Saskatchewan. The pilot was the sole occupant on board.

At 0816,¹ the pilot called the Edmonton Flight Information Centre to file his VFR flight plan. The planned route was from CFN5 to Slave Lake Airport (CYZH), Alberta, then to Lloydminster Airport (CYLL), Alberta, and finally to CYXE. The planned altitude for the flight was 5500 feet above sea level (ASL). During the call, the flight service specialist offered to provide a weather briefing, but the pilot declined and informed the specialist that he had already retrieved weather information for the airports along the route and concluded that the conditions met VFR minima; however, he recognized that it might not be possible to reach his planned altitude owing to clouds.

¹ All times are Mountain Daylight Time (Coordinated Universal Time minus 6 hours).


The pilot had a tablet on board with a current subscription to a commercially available flight planning program. The investigation was unable to confirm whether or not the pilot used that program to obtain weather information. However, the investigation revealed that the pilot called his family before departure and told them that he was aware of poor weather on his planned route, but that he would work his way around it. He had flown this route many times.

The aircraft departed at 0900 in visual meteorological conditions and initially climbed to 3500 feet ASL on a southerly heading (figures 1 and 2). Along the route to CYZH, the aircraft reached an altitude of 4000 feet ASL before descending, likely due to cloud ceilings. When the aircraft was 14 nautical miles (NM) north of CYZH, the pilot changed the destination in the GPS (global positioning system) from CYZH to CYLL. The aircraft's track then turned to the east toward CYLL and toward rising terrain. At this time the aircraft was at 3000 feet ASL or 500 feet above terrain.

Figure 1. Map showing the occurrence flight track (Source: Google Earth, with TSB annotations)




Figure 2. Graph showing the terrain and vertical flight path profile, with altitudes indicated in feet above sea level and distances indicated in statute miles from La Crête Aerodrome (Source: TSB, based on data from the aircraft's digital engine monitor)



At 1011:40, the aircraft climbed to 3550 feet ASL and its ground speed decreased from 125 knots to 68 knots. The aircraft then started a descent at 1011:59 and descended until shortly after 1012:09, when it impacted terrain in a wooded area at approximately 3200 feet ASL (Figure 3). GPS data from

the digital engine monitor² showed that the aircraft's descent angle before it hit trees was about 15°. The average descent rate was 1680 fpm until a few seconds before impact, when it increased to over 2000 fpm. The pilot was fatally injured. The aircraft was destroyed. The emergency locator transmitter activated.

Figure 3. Aerial photo showing the flight path before the collision with terrain (Source: Google Earth, with TSB annotations)



Given the weather conditions, search and rescue (SAR) aircraft, based at Slave Lake and Cold Lake, Alberta, as well as Comox, British Columbia, were grounded at the time of the occurrence and an air search of the area was not possible. As a result, first responders could not locate the site on the day of the occurrence. The accident site was located the next day, and was reached by SAR technicians 2 days after the occurrence.

Pilot

The pilot held a private pilot licence and his Category 3 medical certificate was valid. He had obtained an instrument rating in 1979. Records indicate that he had not exercised the instrument rating privileges in the preceding 5 years and did not meet the recency requirements to do so.

Records also indicate that the pilot had accumulated approximately 2800 hours of flying time, 1259 of which were in the occurrence aircraft or other Mooney M20 aircraft.

Aircraft information

The Mooney M20C is a low-wing, single-engine, 4-seat, general aviation aircraft with retractable tricycle landing gear. The occurrence aircraft was manufactured in 1964.

² Electronics International CGR-30P digital engine monitor.

The investigation did not identify any issues related to aircraft equipment, maintenance, or certification that would have prevented the aircraft from operating normally during the occurrence flight.

The occurrence aircraft was equipped with a Garmin GNS430 GPS. In addition to navigation data, this unit has the capability to provide pilots with visual terrain advisories; however, it is not certified as a terrain awareness and warning system in accordance with technical standing order CAN-TSO-C151d.³ The investigation was unable to determine whether or not this feature was in use at the time of the occurrence.

The aircraft was not equipped with a flight data recorder or a cockpit voice recorder, nor was it required to be by regulation.

Impact and wreckage information

The area around the accident site was heavily treed. Damage to the aircraft is consistent with the aircraft striking trees in a right-wing-low attitude. Following the impact with the trees, the right wing tip broke off and the aircraft continued to the ground on an 18° trajectory. The aircraft collided with the ground about 45 feet from where it first struck the trees. This impact is consistent with a loss of control of the aircraft.

The aircraft's instruments were found either in the instrument panel or in the wreckage near the panel. The altimeter was set to 29.69 inches of mercury (inHg).⁴ The investigation determined there were no signs of pre-impact mechanical failure or system malfunction. The damage to the engine and propeller indicates that power was being produced during the impact sequence. There was no indication of fire in the wreckage.

Weather

There is no weather reporting at CFN5. At the time of departure, the aerodrome routine meteorological report (METAR) issued at High Level Airport (CYOJ), Alberta, the nearest reporting station (32 NM to the northwest of CFN5), indicated:

- wind from 360° true (T) at 9 knots
- visibility 15 statute miles (SM)
- broken ceiling at 11 000 feet above ground level (AGL), overcast cloud layer at 26 000 feet AGL
- temperature 11 °C, dewpoint 8 °C
- altimeter setting 29.86 inHg

The aerodrome forecast (TAF) issued at 0639 indicated that conditions at CYZH at 0900 would be:

- wind from 050°T at 8 knots
- visibility 6 SM in light rain and mist

³ A technical standing order (TSO) is a minimum performance standard, defined by Transport Canada, used to evaluate an appliance or a part. CAN-TSO-C151d applies to terrain awareness and warning systems.

⁴ This was the altimeter setting for Slave Lake Airport, and would have provided an accurate indication of altitude assuming no anomalies with the aircraft's altimeter or static system.

- scattered cloud layer at 800 feet AGL, overcast ceiling at 1200 feet AGL

Temporarily between 0900 and 1900 on the day of the occurrence, the TAF indicated:

- visibility 3 SM in light rain showers and mist
- broken ceiling at 800 feet AGL, overcast cloud layer at 1200 feet AGL

There was a 30% probability during this time frame for visibility of 3 SM in thunderstorms, rain, and mist, and an overcast ceiling at 2000 feet AGL with embedded cumulonimbus clouds.

The forecast for the route indicated on the graphic area forecast (GFA) (Figure 4) was:


- overcast cloud ceilings between 4000 and 6000 feet ASL with tops at 20 000 feet ASL
- frequent altocumulus castellanus clouds with tops at 24 000 feet ASL
- visibility 3 SM to more than 6 SM in rain showers or light rain showers with mist

The GFA also indicated isolated cumulonimbus clouds with tops at 34 000 feet ASL giving visibilities of 1 SM in thunderstorms, rain, and mist. During those periods patchy cloud ceilings were expected between 600 and 1200 feet AGL.

At the time of the occurrence, the automated weather observation system (AWOS) at CYZH (12 NM to the southwest of the accident site) reported:

- wind from 270°T at 6 knots
- visibility 9 SM
- overcast ceiling at 1500 feet AGL
- temperature 13 °C, dewpoint 12 °C
- altimeter setting 29.68 inHg

Figure 4. Graphic area forecast valid at 0600 Mountain Daylight Time on 31 August 2021. Yellow circle denotes accident site location. (Source: NAV CANADA, with TSB annotations)



Visual flight rules in deteriorating weather conditions

The hazards associated with continuing VFR flight into instrument meteorological conditions are well documented. According to data collected by the TSB from 2000 to 2019, accidents involving flights that depart under visual meteorological conditions and continue to a point where pilots lose visual reference with the ground have a high number of fatalities. Over this 20-year period, these types of accidents resulted in 115 fatalities.

TSB laboratory reports

The TSB completed the following laboratory reports in support of this investigation:

- LP108-2021 – NVM Recovery - iPad
- LP113-2021 – Log book Restoration
- LP116-2021 – NVM Recovery - Digital Engine Monitor
- LP146-2021 – Instruments Analysis

Safety message

Pilots are reminded that flying VFR in marginal weather conditions, such as low ceilings, is challenging, especially when flying over rising terrain. Pilots need to plan ahead and consider strategies to avoid adverse weather, as well as have alternate plans should such weather be encountered. VFR flights that continue into instrument meteorological conditions often result in a fatal collision with terrain or a loss of control due to lost visual references.

This report concludes the Transportation Safety Board of Canada's investigation into this occurrence. The Board authorized the release of this report on 02 March 2022. It was officially released on 17 March 2022.

Visit the Transportation Safety Board of Canada's website (www.tsb.gc.ca) for information about the TSB and its products and services. You will also find the Watchlist, which identifies the key safety issues that need to be addressed to make Canada's transportation system even safer. In each case, the TSB has found that actions taken to date are inadequate, and that industry and regulators need to take additional concrete measures to eliminate the risks.

ABOUT THIS INVESTIGATION REPORT

This report is the result of an investigation into a class 4 occurrence. For more information, see the Policy on Occurrence Classification at www.tsb.gc.ca

The Transportation Safety Board of Canada (TSB) investigated this occurrence for the purpose of advancing transportation safety. It is not the function of the Board to assign fault or determine civil or criminal liability.

TERMS OF USE

Use in legal, disciplinary or other proceedings

The *Canadian Transportation Accident Investigation and Safety Board Act* states the following:

- 7(3) No finding of the Board shall be construed as assigning fault or determining civil or criminal liability.
- 7(4) The findings of the Board are not binding on the parties to any legal, disciplinary or other proceedings.

Therefore, the TSB's investigations and the resulting reports are not created for use in the context of legal, disciplinary or other proceedings.

Notify the TSB in writing if this investigation report is being used or might be used in such proceedings.

Non-commercial reproduction

Unless otherwise specified, you may reproduce this investigation report in whole or in part for non-commercial purposes, and in any format, without charge or further permission, provided you do the following:

- Exercise due diligence in ensuring the accuracy of the materials reproduced.
- Indicate the complete title of the materials reproduced and name the Transportation Safety Board of Canada as the author.
- Indicate that the reproduction is a copy of the version available at [URL where original document is available].

Commercial reproduction

Unless otherwise specified, you may not reproduce this investigation report, in whole or in part, for the purposes of commercial redistribution without prior written permission from the TSB.

Materials under the copyright of another party

Some of the content in this investigation report (notably images on which a source other than the TSB is named) is subject to the copyright of another party and is protected under the *Copyright Act* and international agreements. For information concerning copyright ownership and restrictions, please contact the TSB.

Citation

Transportation Safety Board of Canada, *Air Transportation Safety Investigation Report A21W0071* (released 17 March 2022).

Transportation Safety Board of Canada
200 Promenade du Portage, 4th floor
Gatineau QC K1A 1K8
819-994-3741; 1-800-387-3557
www.tsb.gc.ca
communications@tsb.gc.ca

© Her Majesty the Queen in Right of Canada, as represented by the Transportation Safety Board of Canada, 2022

Air transportation safety investigation report A21W0071

Cat. No. TU3-10/21-0071E-PDF

ISBN: 978-0-660-42265-7

This report is available on the website of the Transportation Safety Board of Canada at www.tsb.gc.ca

Le présent rapport est également disponible en français.